ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0404, W0413, W0304, W0484, W0421, W0401, W0486, W

Street Name
NA, 3rd Crs, V S T Opposite, 3rd Crs, 8th A Crs

Significant Landmark
Singapura main layout main roads

Segment No.
11/C-W0404/S040915

Total Length (m)
607.00

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	171.17	77.538907	13.076364	77.540470	13.076155	W0027	DEAD END
2	408.92	77.538723	13.076643	77.542395	13.076157	W0027	DEAD END
3	26.91	77.540884	13.076613	77.540871	13.076370	W0494	W0304

Work Details

History of Road / Lane / Circles

Name of the Work
Road Development and asphalting work at Singapura main layout main roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1999000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Road Development and asphalting work at Singapura main layout main roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-15-000035

Work Order No.
EE/BTP/BBMP/E-PMT/62/2015-16

Work Order Date
29/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
30/07/2015

Defect Liability Period To
29/07/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00

Phone No.	E-Mail ID
9731567144	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH
Date of Inspection	**Remarks**	
18/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0404, W0413, W0304, W0484,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	VASU K M	18/03/2017	17/04/2017	COMPLETED
AEE	MAHADEV	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0404, W0413, W0304, W0484,